

Required Equipment for Chainsaw Sawyer & Swamper

This is a list of approved equipment that is needed to use Chainsaw or Cross Cut in the forest.

Chaps:

It is required that chaps go down the leg to the boot, most people wear a 36" chap. UL certified to ASTM standards

<http://www.baileysonline.com/Safety-First-Aid/Chainsaw-Protective-Clothing/Chainsaw-Chaps/Labonville-Chainsaw-Chaps/Labonville-Apron-Wrap-Chainsaw-Safety-Chaps.axd>

Axe:

The Dayton style head is perfect for cleaning out undercuts and the 5 lb square back head will drive wedges with power -

<http://www.baileysonline.com/Forestry-Woodcutting/Axes-Mauls/Falling-Logging-Axes/WoodlandPRO-Fallers-Axe-5-lbs-with-28-Hickory-Handle-WP-1028.axd>

Or:

<http://www.baileysonline.com/Forestry-Woodcutting/Axes-Mauls/Falling-Logging-Axes/Council-Tool-Dayton-Axe-5-lbs-with-28-Straight-Handle-50DR28S.axd>

Wedges: 3

8 inch:

<http://www.baileysonline.com/Forestry-Woodcutting/Felling-Wedges/K-H-Felling-Wedges/K-H-8-Red-Head-Falling-Wedge-Each-15320.axd>

10 inch:

<http://www.baileysonline.com/Forestry-Woodcutting/Felling-Wedges/K-H-Felling-Wedges/K-H-10-Red-Head-Falling-Wedge-Each-15321.axd>

12 inch:

<http://www.baileysonline.com/Forestry-Woodcutting/Felling-Wedges/K-H-Felling-Wedges/K-H-12-Red-Head-Falling-Wedge-Each-15322.axd>

Hard Hats:

<http://www.baileysonline.com/Safety-First-Aid/Hard-Hats-Helmets/Forestry-Helmets/Husqvarna-Pro-Forest-Helmet-System-577764601.axd>

<http://www.baileysonline.com/Safety-First-Aid/Hard-Hats-Helmets/Hard-Hats/Husqvarna-Pro-Forestry-Hard-Hat---Orange.axd>

Hearing protection:

<http://www.baileysonline.com/Safety-First-Aid/Hearing-Protection/Muffs/Aearo-Peltor-H31A-Hearing-Protection.axd>

Or

Foam ear plugs:

<http://www.baileysonline.com/Safety-First-Aid/Hearing-Protection/Plugs/Deplug-Tapered-Ear-Plugs-w-cords-box-of-100.axd>

Safety Glasses:

<http://www.baileysonline.com/Safety-First-Aid/Safety-Glasses/Safety/Smith-and-Wesson-Anti-Fog-Elite-Clear-Safety-Glasses.axd>

Boots have to be 8 inch high

Clothing must be in good condition and free of hanging strings